



BANEDANMARK

ORF

Operational Rules for fjernbane

ORF-24-2 valid from 14.10.2024

Changes since previous version

IN.60

Change per 2024-10-14:

Roles
The role "guest" is removed.

Rules for Working in the Infrastructure
The section updated to describe what to do if persons without a valid ID cards is called upon to assist in acute corrective maintenance.

Roles

RF.57

Deleted

Change per 2024-10-14:

~~Visitor~~
Deleted

RF.58

DEFINITION

Deleted

Change per 2024-10-14:

~~A Visitor is a person assigned to perform a task within the safety distance of 4 metres from the nearest rail, but with a special permission to deviate from the requirement of possessing a valid railway ID card. A Visitor always receives an instruction and is always accompanied by a staff.~~

Deleted

Rules for Working in the Infrastructure

TW12

Track workers competencies

TW19

Persons without an ID card

TW20

Acute corrective maintenance

TW21 **PICOSS**
 O&M coordinator

Persons without valid ID cards who are called upon to assist in acute corrective maintenance tasks or in emergencies must receive special safety instructions relating to the specific task and the specific geographical location from the PICOSS.

The person calling on assistance is responsible for briefing all personnel with the safety instructions before work is commenced.

If assistance is called in connection with infrastructure work overseen by a PICOSS, it is always the responsibility of the PICOSS to carry out the safety instructions.

Persons without valid ID cards must be accompanied by a railway safety trained member of staff

The person accompanying must be in the immediate vicinity of the person being accompanied.

Change per 2024-10-14:

Persons without valid ID cards who are called upon to assist in acute corrective maintenance tasks or in emergencies must receive special safety instructions relating to the specific task and the specific geographical location from the PICOSS.

The person calling on assistance is responsible for briefing all personnel with the safety instructions before work is commenced.

If assistance is called in connection with infrastructure work overseen by a PICOSS, it is always the responsibility of the PICOSS to carry out the safety instructions.

Persons without valid ID cards must be accompanied by a railway safety trained member of staff

The person accompanying must be in the immediate vicinity of the person being accompanied.

TW22 **Deleted**

Change per 2024-10-14:

~~Visitors Deleted~~

TW23 **PICOSS** Deleted

Change per 2024-10-14:

~~Visitors without ID cards must be accompanied by a railway safety trained member of staff.~~

~~The railway safety educated member of staff is responsible for briefing the instructions to all visitors.~~Deleted